


Audit Date: 20 July 2019	Registration numbers: F_IAR_80483
Audit Team: Abdullah Muktadir	Facility Name: Modern Needle Craft Ltd.

#### A. Non Compliance Photos:

	Nil	Nil
Compressor not fenced	N/A	N/A

#### A. General Facility Tour Photos:

		
Facility name	Facility entrance	Facility building
		
Production shed building	Three Storied RCC Building (Abandoned building 4)	Security area

Audit Date: 20 July 2019	Registration numbers: F_IAR_80483
Audit Team: Abdullah Muktadir	Facility Name: Modern Needle Craft Ltd.

		
Embroidery section	Accessories store	Evacuation plan
		
Main aisles	Staircase	Fire alarm switch
		
Fire alarm	Fire control panel	Visual fire alarm



Audit Date: 20 July 2019	Registration numbers: F_IAR_80483
Audit Team: Abdullah Muktadir	Facility Name: Modern Needle Craft Ltd.

		
Fire extinguisher	Fire fighting equipments	Fire hose cabinet
		
Smoke detector	Fire resistant door at fire exit	Illuminated exit sign
		
Emergency light	P.A (Public Address) system	First aid box

Audit Date: 20 July 2019	Registration numbers: F_IAR_80483
Audit Team: Abdullah Muktadir	Facility Name: Modern Needle Craft Ltd.

## B. General Facility Tour Photos: (con't)




		
Drinking water facility	Electrical wiring box	No smoking sign posted
		
Dining area	Canteen	Medical area
		
Notice board	Eye wash station	Toilet area



Audit Date: 20 July 2019	Registration numbers: F_IAR_80483
Audit Team: Abdullah Muktadir	Facility Name: Modern Needle Craft Ltd.

		
Suggestion box	Time keeping system	Generator area
		
Transformer area	Chemical store	CCTV Camera
		
Personal box	Danger sign posted	Fire pump area

Audit Date: 20 July 2019	Registration numbers: F_IAR_80483
Audit Team: Abdullah Muktadir	Facility Name: Modern Needle Craft Ltd.

		
Gong bell	Shed 5: Vacant and under construction	Firefighter identified

**C. Best Practice Photos: Nil**